

Airport Campus and Approach Roadways

Review/Analysis/Conceptual Design of Vehicular Wayfinding Signage

Task: Wayfinding Discovery and Analysis

OCTOBER 2013

Presented by:




- General Analysis
 - Evaluation Criteria
- Roadway Standards
 - MUTCD / Caltrans
- Analysis Summary
 - Approach Freeways/Roads
 - Airport Campus Roads
 - Five Select Drive-Throughs from Major Freeways/Roads:
 - South on Interstate 5
 - North on Interstate 5
 - South on 163
 - North on Pacific Highway (SD Convention Center/Embarcadero)
 - East on North Harbor Drive

Drive Through 1 - Summary

I-5 (Southbound) \rightarrow Sassafras St. Exit \rightarrow RCC / Laurel St. \rightarrow N. Harbor Dr. (East Airport Entry)

Analysis – Approach Roads

Drive-Through 1





- 1. Universal symbols not used
- 2. RCC message may be desirable here

Repercussions/Considerations

- Opt. 1:
 - New face may be req'd
- Opt. 2:
 - New face may be req'd
 - New header panel may affect structure load
 - Existing structure engineering must be verified (may require new structure)

Map data: © 2013 Google, Sanborn, INEGI Street view images: © 2013 Google, INEGI



Conceptual Recommendation: Opt. 2 San Diego **Airport** Ä Rental Car Return USE Sassafras St. • New sign panel on new post • Located slightly further up road (approx.

Observations

- 1. Visually lost next to other sign panels
- 2. Format differs from other directionals
- 3. Small, very easy to miss

Repercussions/Considerations

- Opt. 1:
 - New faces req'd
 - I-5 panels must be moved up or to new post
 - Light pole must be structurally verified to allow for new panels
- Opt. 2:
 - New location may require field verification/code considerations
 - Break-away post system

pole

shown)

 Move I-5 sign panels up (or to new separate post)

Satellite data: © 2013 Google, SIA, NOAA, U.S. Navy, NGA, GEBCO, Landsat, USGS



New sign panel on new post




Observations

- 1. No sign currently located
- Opportunity for point of wayfinding reinforcement to Airport
- 3. Opportunity for directional messaging to RCC (for W.B. traffic on Laurel Street approaching primary decision point)


- New location may require field verification/code considerations
- Break-away post system

Drive-Through 2a - Summary

I-5 (Northbound) \rightarrow Hawthorn St. Exit \rightarrow Pacific Hwy \rightarrow Laurel St. \rightarrow RCC











Satellite data: © 2013 Google, SIA, NOAA, U.S. Navy, NGA, GEBCO, Landsat, USGS








Satellite data: © 2013 Google, SIA, NOAA, U.S. Navy, NGA, GEBCO, Landsat, USGS





Drive-Through 2b - Summary


I-5 (Northbound) \rightarrow Sassafras St. / India St. Exit \rightarrow Sassafras St. \rightarrow RCC












Drive-Through 3 - Summary

Hwy 163 (Southbound thru Balboa Park Area) → merge w/I-5 (Northbound) → Hawthorn St. Exit



allow message to fit




Observations

- 1. No sign currently located
- Opportunity for early queuing/wayfinding reinforcement


- New posts and panel req'd
- New location may require field verification/code considerations
- Break-away system






Drive-Through 4 - Summary

W. Market St. \rightarrow W. Harbor Dr. \rightarrow Pacific Hwy \rightarrow Laurel St./N. Harbor Dr. (East Entrance)








- 1. No sign currently located
- Opportunity for improved directional messaging to Airport (prior to primary decision point at Pacific Hwy)

- New panels req'd
- Light pole must be structurally verified to allow for new panels



- 1. Replace current sign
- Opportunity for improved wayfinding reinforcement to match other Airport trailblazers

Repercussions/Considerations

- New panel req'd
- Light pole must be structurally verified to allow for new panels

lata: © 2013 Google, Sanborn, INEGI view images: © 2013 Google, INEGI

Satellite data: © 2013 Google, SIA, NOAA, U.S. Navy, NGA, GEBCO, Landsat, USGS

• New sign panels on existing light post




Observations

- 1. No sign currently located
- Opportunity for point of improved directional messaging to Airport (prior to primary decision point)
- 3. Opportunity for directional messaging to RCC (for N.B. traffic on Pacfic Hwy approaching primary decision point)

- New panels req'd
- Light pole must be structurally verified to allow for new panels

Drive-Through 5 - Summary

Nimitz Blvd. \rightarrow N. Harbor Dr. (West Airport Entry) \rightarrow Grape St. \rightarrow Pacific Hwy. \rightarrow RCC



• New sign panels on new post



Observations

 Trailblazing to Rental Car Return does not currently exist

- New post and panels req'd
- New location may require field verification/code considerations
- Break-away post system



- 1. Message on right will no longer be accurate
- 2. Universal symbols not used

Repercussions/Considerations

- Re-face of existing
- New face may be required

END

Map data: © 2013 Google, Sanborn, INEGI Street view images: © 2013 Google, INEGI Satellite data: © 2013 Google, SIA, NOAA, U.S. Navy, NGA, GEBCO, Landsat, USGS



 Reinforcement/trailblazing to Rental Car Return may be needed

Repercussions/Considerations


- New faces req'd
 - Light pole must be structurally verified to allow for new panels



• New sign panel mounted to light pole



• Alternate sign panel option



- 1. No sign currently located
- Opportunity for point of wayfinding reinforcement to RCC entrance

- New post and panel req'd
- New location may require field verification/code considerations
- Break-away system

Thank You



Airport Campus and Approach Roadways

Review/Analysis/Conceptual Design of Vehicular Wayfinding Signage

Task: Wayfinding Discovery and Analysis

AUGUST 2013

Presented by:

