
Appendix B - Best Management Practices

BMP SR01	SPILL PREVENTION, CONTROL, AND CLEAN-UP			
	ce the discharge of pollutants to storm water resulting from spills, oper cleanup of significant and other materials.	TARGETED ACTIVITIES: → Aircraft Deicing/Anti-Icing → Aircraft Lavatory Service → All Fueling → All Maintenance → All Storage → All Washing → Cargo Handling → Equipment Cleaning → Fire Fighting Equip. Testing → Floor Washdowns → Garbage Collection → Outdoor Washdown → Painting/Stripping → Runway Rubber Removal		
POLLUTION PREVENTION:		POLLUTANTS of CONCERN:		
	Implement the following pollution prevention practices and BMPs to prevent spills and leaks of significant and other materials to the storm water collection system: Provide formal training in execution of the Spill Plan(s) to key personnel, with additional training for first responder level personnel. All employees should have basic knowledge of spill control procedures and potential dangers of spills on human health and the environment. Incorporate spill control procedures in regular safety meetings to reinforce practices. Maintain an inventory of appropriate cleanup materials and equipment on-site and strategically deploy cleanup materials and equipment based on the type and quantities of chemicals present.	→ Aircraft Fire Fighting Foam → Battery Acid → Cleaning Solution → Deicing/Anti-Icing Fluid → Fuel → Heavy Metals → Hydrocarbons → Lavatory Chemicals → Metals → Oil and Grease → Paint → Pesticides/Herbicides/ Fertilizers → Potable Water System Chemicals → Solvents → Vehicle Fluids		
OPERATIONS:		APPLICABLE TENANTS/		
- 03	Develop, implement and keep current Spill Plan, and develop facility spill prevention and response procedures. Post a summary of the Spill Plan and spill response procedures, at key locations, identifying the spill cleanup coordinators, location of cleanup equipment, and phone numbers of regulatory agencies to be contacted in the event of a spill. Train relevant employees and contractors in the implementation of the Spill Plan, if applicable, or spill control procedures.	DEPARTMENTS: → ACE → Air Canada → Alaska → Allegiant → Allied Aviation → American Airlines → ARFF → Bradford → British Airways → Cartwright		
- 04 🗌	Use leak and spill prevention devices.	, Cartwright		

Individual BMP From:

Appendix B - Best Management Practices

BMP SR01	SPILL PREVENTION, CONTROL, AND CLEAN-UP				
- 05 🗌	Place adequate spill kits in appropriate locations.	>	Conrac Delta		
- 06	Notify Airport Operations (619-400-2710), the Airport Authority Environmental Affairs Department (619-400-2784), and any agencies or companies identified in the Spill Plan or facility spill prevention and response procedures in the event of a spill.	+ + + +	DHL Edelweiss FedEx Flagship Frontier		
- 07 🗔	In the event of a spill or release, immediately follow procedures identified in the Spill Plan or facility spill prevention and response procedures.	+ +	Hawaiian HFF HMS Host JAL		
- 08 🗌	Use only dry cleaning methods.		Jet Blue Lufthansa		
- 09 🗌	Properly dispose of all used spill control and clean-up materials.		Menzies Mission Yogurt		
- 10	Waste water from washing activities is captured by vacuum and properly disposed of, or is diverted to a structural treatment control, sanitary sewer, or dead end sump with pump.	ナナナナナナナナナ	SDCRAA Siemens Signature Southwest SP Plus Spirit SSP Sun Country United UPS WestJet		
STRUCTURAL TREATMENT BMPs: Refer to BMP TC01 for information on structural treatment BMPs.					
on a daily basis spill pallets, ou lockers, bermed and drums.	ENCIES/EQUIPMENT/TOOLS: Spill prevention and control occurs and up is as needed. Equipment/tools to implement BMPs include atdoor sheds, overpack containers, tarps, flammable materials storage and or containment areas, fiber rolls, shop vacuums, spill kits, brooms, D LOCATIONS TO IMPLEMENT SPILL PREVENTION, ND CLEANUP BMPs: Implement BMPs for the prevention of non-storm water discharges from spills, leaks or improper cleanups at the designated areas as shown in the attached map.				
Date:		Versi	ion: 2.0		



Individual BMP From:

Appendix B - Best Management Practices

Intentionally Left Blank