

## Virgin America Airlines

SIC Codes	4512, 4522	Contact Information	
Primary Activity	Passenger Carrier	Ron Cook	Environmental Contact
Drainage Areas	12	P 6192206770	C 6505206309
Nearest MS4 Inlet	< 200 ft.	ron.cook@virginamerica.com	
Address	3707 North Harbor Dr. #104	Nadya Benitez	Supervisor
	San Diego, CA 92101	P 6192206771	
		nadya.benitez@virginamerica.com	

### Facility Description and Activities

\*\*Expected to move from Gate 25 to gate 35 by Nov 15, 2014, check with tenant for move status. Gates, offices, ramps are all planned to move. No longer operates out of Gate 26.

1. DAL Global Services (DGS) performs ground handling and equipment maintenance.
2. Pacific Aircraft Maintenance performs minor aircraft maintenance at gate. 2. ASIG performs aircraft fueling.
3. A small amount of universal waste collected by airport security checks is stored in a flammable locker inside the bag room outside Virgin America's office. Ocean Blue picks up as needed.
4. One spill cart is located by Gate 2
5. SDCRAA spill kit is located at Gate 26, which is also used in case of an emergency. 5. Virgin performs a monthly stormwater prevention assessment of operational area.
6. No lavatory and catering services are performed in San Diego.
7. ELS is contracted to maintain the jet bridge and belts.
8. Virgin America owns one vehicle. It is kept in very good condition. Fueling and maintenance is performed offside.

### Significant Materials/Activities Potentially Exposed to Storm Water

#### Potential Pollutant Sources

Drainage system maintenance  
Equipment storage  
Fluid leaks  
Fuel spills,Fuel transfer  
Outdoor waste storage  
Potable water flushing  
Trash collection

#### Potential Pollutants

Anti Freeze  
Cleaning Solutions  
Food Waste  
Fuel  
Lubricants  
Oil & Grease  
Recyclables  
Trash

## Best Management Practices Applicable to Facility

ActivitiesBMPs

Non-Storm Water Management	SC01 - 1, 2, 4
Outdoor Equipment Ops Maintenance Areas	SC02A - 1, 2
Aircraft, Ground Vehicle & Equipment Maintenance	SC02B - 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12
Aircraft, Ground Vehicle & Equipment Fueling	SC03 - 1, 2, 4, 5, 6, 8
Aircraft, Ground Vehicle & Equipment Cleaning	SC04 - 1, 2
Outdoor Loading/Unloading of Materials	SC06 - 6, 7
Outdoor Material Storage	SC07 - 1, 2, 3
Waste Handling & Disposal	SC08 - 1, 2, 3, 4, 5, 8, 9, 10, 11, 12, 14
Employee Training	SC10 - 1, 2, 4
Potable Water System Flushing	SC14 - 1, 2, 3
Drainage System Maintenance	SC17 - 2, 7
Housekeeping	SC18 - 1, 2, 3, 4, 5, 6, 7, 9
Safer/Alternative Products	SC19 - 1, 2
Spill Prevention, Control & Clean Up	SR01 - 1, 2, 3, 4, 5, 6, 7, 8, 9

\* Appendix B provides descriptions for each BMP category.

Structural Control measures used by facility:

Materials Storage Area

Gate 35 office

Materials Storage Amounts

No materials recorded over 55 gallons

Small amount of universal waste stored in flammable locker at Gate 35 office

Shipping/Receiving Area

Not recorded



PROJECT NO.:	5025-13-0031
DATE:	JUNE 2015
DRAWN BY:	RMH
CHECKED BY:	AJA

amec foster wheeler



**Virgin America**  
**Operating Areas**  
**San Diego International Airport**

FIGURE

**E-36**

Intentionally Left Blank