

British Airways Airlines

SIC Codes 4512, 4522
 Primary Activity Passenger Carrier
 Drainage Areas 8, 12
 Nearest MS4 Inlet < 200 ft.
 Address 3707 North Harbor Dr. #117
 San Diego, CA 92101

Contact Information
 David Johnson Manager - Station
 C 6192521820
 d.johnson@gsintlinc.com

 Timothy Hosea P Manager - General
 6192780797 C 6199125308
 timothy.hosea@ba.com

Facility Description and Activities

1. British Airways operates out of gate 20 in Terminal
2. British Airways' aircraft fueling is carried out by ASIG.
3. British Airways has only one (1) vehicle and all maintenance pertaining to said vehicle is performed off airport.
4. Minor aircraft maintenance is performed at the gate. Major aircraft maintenance is performed on the north ramp. Major maintenance is performed by a BA/AA engineer, while minor maintenance is performed by a local mechanic.
5. Aircraft and vehicles are not washed on site.
6. Five waste accumulation areas - one between Gates 31 and 32, two inside auto shop, one outside of auto shop, and one in stores next to auto shop.
7. Heritage Environmental Services collects British Airways used oils monthly.
8. All freight/cargo handling is carried out by CAS and ATS. CAS occasionally receives deliveries (i.e. cabin supplies) for British Airways.
9. Tenant has used the Airport Storm Water Management Plan, and has an Emergency Contingency Plan, and a Spill Prevention, Control, and Countermeasure Plan.
10. Flying Foods is a vendor for BA.
11. GSI manages employees and equipment for BA.
12. GAT performs lavatory services.
13. No equipment cleaning is performed currently. BA may contract power wash cleaning services for a quarterly wash and/or steam clean. Company berms the area and vacuums the water.

Significant Materials/Activities Potentially Exposed to Storm Water

Potential Pollutant Sources

Aircraft sanitary services
 Equipment storage

Potential Pollutants

Anti Freeze
 Cleaning Solutions

Fluid leaks
 Fuel spills, Fuel transfer
 Outdoor waste storage
 Potable water flushing
 Trash collection

Tenant Summaries

Fuel
 Hydraulic Fluids
 Lavatory Chemicals
 Lavatory Truck Wash Water
 Lavatory Wastes
 Lubricants
 Oil & Grease
 Recyclables
 Trash

Best Management Practices Applicable to Facility

Activities

Non-Storm Water Management
 Outdoor Equipment Ops Maintenance Areas
 Aircraft, Ground Vehicle & Equipment Maintenance
 Aircraft, Ground Vehicle & Equipment Fueling
 Waste Handling & Disposal
 Employee Training
 Lavatory Service Operation
 Potable Water System Flushing
 Housekeeping
 Safer/Alternative Products
 Spill Prevention, Control & Clean Up

BMPs

SC01 - 1, 2, 4
 SC02A - 1, 2
 SC02B - 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13
 SC03 - 1, 2, 4, 5, 6, 8
 SC08 - 1, 2, 3, 4, 5, 6, 8, 9, 10, 11, 12, 14
 SC10 - 1, 2, 3, 4
 SC11 - 3, 4, 5, 6, 7, 8, 9, 10
 SC14 - 1, 2, 3
 SC18 - 1, 2, 3, 4, 5, 6, 7, 8, 9
 SC19 - 1, 2
 SR01 - 1, 2, 3, 4, 5, 6, 7, 8, 9

* Appendix B provides descriptions for each BMP category.

Structural Control measures used by facility:

Materials Storage Area

No major material storage areas

Materials Storage Amounts

No materials over 55 gallons stored for daily operations

Shipping/Receiving Area

CAS (at Landmark) receives occasional shipments for BA



PROJECT NO.:
5025-13-0031

DATE:
JUNE 2015

DRAWN BY:
RMH

CHECKED BY:
AJA



**British Airways
Operating Areas**

San Diego International Airport

FIGURE
E-10

Intentionally Left Blank