

Allegiant Air

| | | | |
|--------------------------|--|---------------------------------|---------------------|
| SIC Codes | 4512, 4522 | Contact Information | |
| Primary Activity | Passenger Carrier | Ken Sturgill | General Manager |
| Drainage Areas | 08, 12 | P 6192200164 | C 7757710699 |
| Nearest MS4 Inlet | 200 - 1000 ft. | ksturgill@atsstl.com | |
| Address | 3707 North Harbor Dr. T2E San Diego, CA 92101 | Peter Dreissig | Manager - Regional |
| | | P 7028308270 | C 6128020126 |
| | | peter.dreissig@allegiantair.com | |

Facility Description and Activities

1. All equipment maintenance is done by GES. Daily vital fluid checks are performed by ATS staff and monthly Preventive Maintenance Inspections are conducted by Tom Mascarenas of GES. ATS is a subtenant to Allegiant.
2. Fueling is conducted by Menzies at the Gates. ATS conducts monthly station safety audits which include observing fueling. ATS requests a poundage of fuel to be put into the aircraft prior to each fueling.
3. Cleaning of vehicles is done at the washrack. No aircraft cleaning is performed at SIDA.
4. All aircraft maintenance is performed by Executive Air.
5. Tenant does not have a permanent gate, but frequently uses Gate 30.
6. Potable water is flushed for 30 seconds on the ramp and allowed to evaporate.
7. ATS is a subtenant of Allegiant and performs services above the wing and below the wing for Allegiant.

Significant Materials/Activities Potentially Exposed to Storm Water

Potential Pollutant Sources

Aircraft sanitary services
Cargo handling
Equipment storage
Fluid leaks
Fuel spills, Fuel transfer
Material loading/unloading
Outdoor waste storage
Potable water flushing
Trash collection

Potential Pollutants

Anti Freeze
Battery Acid
Cleaning Solutions
Fuel
Fuel (Diesel)
Hydraulic Fluids
Lavatory Chemical Wastes
Lavatory Chemicals
Lavatory Wastes
Lubricants
Metals
Oil & Grease
Rubber Particulates
Sediment
Trash

Best Management Practices Applicable to Facility

Activities

Non-Storm Water Management
Outdoor Equipment Ops Maintenance Areas
Aircraft, Ground Vehicle & Equipment Maintenance
Electric Vehicle Maintenance
Aircraft, Ground Vehicle & Equipment Fueling
Aircraft, Ground Vehicle & Equipment Cleaning
Outdoor Loading/Unloading of Materials
Outdoor Material Storage


BMPs

SC01 - 1, 2, 4, 7
SC02A - 1, 2
SC02B - 1, 2, 3, 4, 5, 6, 7, 8, 10, 11, 12, 13
SC02C - 1, 2, 3, 4, 5, 6, 8, 9
SC03 - 1, 2, 4, 5, 6, 8
SC04 - 1, 2, 3, 5
SC06 - 1, 2, 3, 4, 6, 7
SC07 - 1, 2, 3, 11, 12

Individual Tenant Summary From Appendix E

| | |
|--------------------------------------|--|
| Waste Handling & Disposal | SC08 - 1, 2, 3, 4, 5, 8, 9, 10, 11, 12, 14 |
| Employee Training | SC10 - 1, 2, 3, 4 |
| Lavatory Service Operation | SC11 - 3, 4, 5, 6, 7, 8, 9, 10, 11 |
| Potable Water System Flushing | SC14 - 1, 2 |
| Housekeeping | SC18 - 1, 2, 3, 4, 5, 6, 7, 8, 9 |
| Safer/Alternative Products | SC19 - 1, 2 |
| Spill Prevention, Control & Clean Up | SR01 - 1, 2, 3, 4, 5, 6, 7, 8, 9 |

* Appendix B provides descriptions for each BMP category.



PROJECT NO.:
5025-18-2002

DATE:
JANUARY 2019

DRAWN BY:
CAB

CHECKED BY:
AA/NP



SAN DIEGO INTERNATIONAL AIRPORT

**Allegiant
Operating Areas**

FIGURE

E-4

Intentionally Left Blank