

## Tenant Summary Sheet

### Tenant:

Allegiant

SIC Code: 4512, 4522

Primary Activity: Passenger Carrier

Drainage Area: 12

Nearest MS4 inlet: 200-1000 feet

Contact: Phil Delk, Station Manager

E: pdelk@atsstl.com, P: 619-220-0164, C: 310-227-7331

Secondary Contact: Alioune Sow, Regional Manager

P: 310-849-9935

Address: 3707 N. Harbor Dr. T2E  
San Diego, CA 92101

### Tenant Description and Primary Industrial Activities:

1. Operate out of Gate 22 but occasionally use 21, 24, or 26. Gate 22 is shared by multiple airlines. Hawaiian operates out of Gate 22 daily and West Jet operates Thursdays and Sundays.
2. All equipment maintenance is done in the GES maintenance shop area by GES. Daily vital fluid checks are performed by ATS staff and monthly Preventive Maintenance Inspections are conducted by Tom Mescuranis of GES. ATS is a subtenant to Allegiant.
3. Fueling is conducted by ASIG at the Gates. ATS conducts monthly station safety audits which include observing fueling. ATS requests a poundage of fuel to be put into the aircraft prior to each fueling.
4. Cleaning of vehicles is done at the triturator facility. No aircraft cleaning is performed at SIDA.
5. All aircraft maintenance is performed by Pacific Aviation.
6. Tenant uses the Airport Storm Water Management Plan, and does not have a Hazardous Materials Business Plan.

### Significant Materials Potentially Exposed to Storm Water:

#### Potential Pollutant Sources

Aircraft Fueling  
Aircraft Maintenance  
Aircraft sanitary services  
Equipment fueling  
Equipment maintenance  
Fluid leaks from aircraft  
Fuel spills  
Vehicle fueling  
Vehicle maintenance  
Vehicle parking

#### Potential Pollutants

Oil and Grease, Sediment, Antifreeze,  
Fuel, Lavatory chemicals, Lavatory wastes,  
Battery acid, Lubricants,

### Best Management Practices and Current Structural Controls:

The list below identifies the BMP categories and specific BMPs that are applicable to Allegiant. Appendix B provides a description of each BMP category.

#### Applicable BMP Categories

Non-Storm Water Management  
Outdoor Equipment Ops and Maintenance Areas  
Aircraft, Ground Vehicle and Equipment Maintenance  
Aircraft, Ground Vehicle and Equipment Fueling  
Waste Handling and Disposal  
Employee Training  
Lavatory Service Operation  
Potable Water System Flushing  
Housekeeping  
Safer/Alternative Products  
Spill Prevention, Control, and Clean-up


#### BMP Number

SC01 - 1, 2, 4  
SC02A - 2, 1  
SC02B - 10, 11, 2, 3, 7, 1, 4, 5, 6, 8  
SC03 - 1, 2, 4, 5, 6, 8  
SC08 - 1, 12, 3, 4, 7, 8, 9  
SC10 - 2, 4, 1  
SC11 - 10, 4, 6, 3, 5, 7, 8, 9  
SC14 - 1  
SC18 - 1, 4, 2, 3, 5  
SC19 - 1, 2  
SR01 - 2, 6, 3, 5, 7, 8, 9

Structural control measures used at Allegiant:



Allegiant



PROJECT NO.:  
5013-11-0003  
DATE: November 2011  
DRAWN BY: RMH  
CHECKED BY: AA



**Allegiant  
Operating Areas**  
San Diego International Airport

FIGURE  
**E-3**