

8

**Appendix B – Best Management Practices**

<b>BMP SC02C</b>	<b>ELECTRIC VEHICLE MAINTENANCE</b>	
appropriate secondary containment devices, spill kits and drums.		
<b>AUTHORIZED ELECTRIC VEHICLE MAINTENANCE LOCATIONS:</b>		
<input type="checkbox"/>	Use only the designated areas for electrical vehicle maintenance as shown in the attached map.	
Date:		Version: 2.0



Tenants Implementing SC-02-C BMP:  
Electric Vehicle Maintenance

1 - Alaska

10 - Delta

19 - SDCRAA

23 - United

27 - Air Canada

35 - Spirit

45 - SSP

78 - Signature

4 - American

18 - ACE

21 - Southwest


26 - Allegiant

29 - West Jet

42 - JAL

50 - Siemens

SDIA Boundary



Aerial Image Source:  
Aerotek Mapping Inc.  
ATM # C0116-008  
Aerial Flight Date: 8/22/2016



Individual BMP From:

**Appendix B – Best Management Practices**

Intentionally Left Blank